

# Inspection Photos

API: 061-06166

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 10/23/2023



## Inspection Photos



**Photo 1.** Facing southwest toward the location. The location fence has been removed and a new fence was installed around the equipment.



## Inspection Photos



**Photo 2.** Facing northwest toward the location. There are unused areas of the location that must be reclaimed.





## Inspection Photos



**Photo 3.** Facing northwest toward the tank battery.



## Inspection Photos



**Photo 4.** This pipe is exposed on the outside of the tank battery and is not contained inside containment,.





## Inspection Photos



**Photo 5.** Facing northeast toward the location. There are unused areas of the location that must be reclaimed.



## Inspection Photos



**Photo 6.** Facing toward the wellhead.

