

Inspection Photos

API: 061-06163

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 10/23/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the location.



Inspection Photos



Photo 2. The fence at the northwest corner needs maintenance.



Inspection Photos



Photo 3. The berm around the tank battery is insufficient to contain a spill. If the tank is not in use then it should be removed..



Inspection Photos



Photo 4. Facing toward the meter run.



Inspection Photos



Photo 5. Facing toward the wellhead. There is a pipe riser with no OOSLAT.

