

Inspection Photos
Location: Drill Site 2
Facility ID: 334549



Photo 1 –Wellhead Placard SMU 3-15-B P&A Wellhead

Photo 2 – SMU 3-15-B Cemented Wellhead, Remediation # 23900

Inspection Photos
Location: Drill Site 2
Facility ID: 334549



**Photo 3 – SMU 3-15-B Cemented Wellhead,
Remediation # 23900**

**Photo 4 – SMU 3-15-B Cemented Wellhead,
Remediation # 23900**

Inspection Photos
Location: Drill Site 2
Facility ID: 334549




Photo 5 – Drill Site # 2, Pit ID 115234

Photo 6 – Drill Site # 2, Pit ID 115234; Remediation # 28884

Inspection Photos
Location: Drill Site 2
Facility ID: 334549



Photo 7 – Drill Site # 2, Pit ID 115234; Remediation # 28884

Photo 8 – Compressor Coolers,

Inspection Photos
Location: Drill Site 2
Facility ID: 334549



Photo 9 – Glycol Spill identified in Inspection Doc # 713600296 has been cleaned

Photo 10 – Glycol Spill identified in Inspection Doc # 713600296 has been cleaned