

# Inspection Photos

Loc: 441082

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/31/2023

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward the location. The disturbed location has not been reclaimed. Previous corrective actions are not completed.





## Inspection Photos



**Photo 2.** Facing northwest at the location. Soils are compacted and the location has not been reclaimed. Previous corrective actions were not performed. Soils must be decompacted by cross ripping to a depth of 18 inches.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:441082 | Date: 10/31/2023



## Inspection Photos



**Photo 3.** Facing east at the location. There are piles of manure and material left on the location. There are undesirable weeds throughout the location.





## Inspection Photos



**Photo 4.** There are gravel and soil piles that remain at the north side of the location. The piles need to be removed. There are undesirable weeds on the piles.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:441082 | Date: 10/31/2023



## Inspection Photos



**Photo 5.** Facing southwest at the north side of the location. There is metal debris which has not been removed.





## Inspection Photos



**Photo 6.** Facing east at the location. Soils are compacted and the location has not been reclaimed.





## Inspection Photos



**Photo 7.** Facing west at the location. Soils are compacted and the location has not been reclaimed.





## Inspection Photos



**Photo 7.** There is a cleanout junction 1850 ft. north of the pipeline which is associated with the former gas compressor station and must be removed. Photo taken from previous inspection.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:441082 | Date: 10/31/2023