

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2023

Submitted Date:

11/05/2023

Document Number:

698601239

**FIELD INSPECTION FORM**

Loc ID 304786 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 17 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274972	WELL	PR	02/21/2005	GW	125-08985	BROWN 32-32	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign located at well fencing. Sign is peeling and unreadable.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 01/05/2024
Emergency Contact Number:			
Comment:	Emergency contact information posted on well sign		Date:
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around wellhead casing		
Corrective Action:	Comply with Rule 1002..(2).D Conduct maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 11/11/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well site. Panels on well side of Pump Jack are damaged and rusted through.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Stock panel safety barrier.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Bradenhead plumbed to surface.		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:	Digital Gas Meter Run. Meter Calibration/Test Log dated 2-8-22. Well Inlet Valve open. Gas Outlet Valve open. Gas meter appears to be past due calibration.		Date:	
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date:	12/07/2023
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Cement pad (Pump Jack).		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods and tubing in the wellbore. Tubing valve open. Casing valve open.		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Gas meter box.		Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric Motor.		Date:	
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			Date:
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 274972 Type: WELL API Number: 125-08985 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403585074	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311120">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311120</a>
698601276	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311116</a>