

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2023

Submitted Date:

11/19/2023

Document Number:

708902279

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 323901 Smelser, Wayne 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

38 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211129	WELL	PR	12/23/1994	GW	045-06888	SAVAGE RMV 15-35	PR
421918	WELL	PR	12/26/2012	GW	045-20449	Savage RWF 343-34	PR
421919	WELL	PR	09/13/2012	GW	045-20450	Savage RWF 312-35	PR
421920	WELL	PR	12/14/2012	GW	045-20451	Savage RWF 542-34	PR
421921	WELL	PR	09/13/2012	GW	045-20452	Savage RWF 42-34	PR
421922	WELL	SI	07/01/2023	GW	045-20453	Savage RWF 522-35	SI
421923	WELL	PR	12/26/2012	GW	045-20454	Savage RWF 323-35	PR
421924	WELL	PR	10/12/2012	GW	045-20455	Savage RWF 422-35	PR
421925	WELL	PR	09/13/2012	GW	045-20456	Savage RWF 441-34	PR
421926	WELL	PR	10/12/2012	GW	045-20457	Savage RWF 342-34	PR
421927	WELL	PR	10/12/2012	GW	045-20458	Savage RWF 442-34	PR
421928	WELL	PR	12/14/2012	GW	045-20459	Savage RWF 22-35	PR
421929	WELL	PR	09/30/2012	GW	045-20460	Savage RWF 23-35	PR
421930	WELL	PR	12/26/2012	GW	045-20461	Savage RWF 412-35	PR
421931	WELL	PR	09/13/2012	GW	045-20462	Savage RWF 12-35	PR
422119	WELL	PR	01/01/2013	GW	045-20492	Savage RWF 313-35	PR
422187	WELL	PR	12/26/2012	GW	045-20520	Savage RWF 413-35	PR

General Comment:

CECMC Inspection Report Summary

On 11/16/2023 at approximately 12:37 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RMV15-35 Pad.

Location # 323901 in Garfield County Colorado.

Please refer to inspection 708901725 conducted on 09/19/2023, previous corrective actions have been completed.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site.

Location is approximately 370 yards from Porcupine Creek.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	ECD & liquid nitrogen tank - hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 17		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 17		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 17		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,

Comment:	Centralized containment
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>211129</u>	Type: <u>WELL</u>	API Number: <u>045-06888</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421918</u>	Type: <u>WELL</u>	API Number: <u>045-20449</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421919</u>	Type: <u>WELL</u>	API Number: <u>045-20450</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421920</u>	Type: <u>WELL</u>	API Number: <u>045-20451</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421921</u>	Type: <u>WELL</u>	API Number: <u>045-20452</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421922</u>	Type: <u>WELL</u>	API Number: <u>045-20453</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <u>Shut In</u>				
<u>Last produced June 2023</u>				
Corrective Action:		Date:		
Facility ID: <u>421923</u>	Type: <u>WELL</u>	API Number: <u>045-20454</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing, well on plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>421924</u>	Type: <u>WELL</u>	API Number: <u>045-20455</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421925 Type: WELL API Number: 045-20456 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421926 Type: WELL API Number: 045-20457 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421927 Type: WELL API Number: 045-20458 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421928 Type: WELL API Number: 045-20459 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421929 Type: WELL API Number: 045-20460 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421930 Type: WELL API Number: 045-20461 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 421931 Type: WELL API Number: 045-20462 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
Facility ID: 422119 Type: WELL API Number: 045-20492 Status: PR Insp. Status: PR				

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
Facility ID:	422187	Type:	WELL
API Number:	045-20520	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Check Dams						
Berms						
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containments
Ditches						
Compaction						Small areas with light compaction
Tracking Pad						Aggregate/gravel based VTC
Sediment Traps						
Gravel						Sparse
		Compaction				
		Gravel				Sparse

Comment: Aggregate/gravel based VTC near entrance to location. Dimensions & details are as follows - approximately 50-54 ft long, 60 ft wide & varying depths from 1-4 inches, depth & length insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902280	Inspection 708902279 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328269
708902281	Inspection 708902279 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328270