



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign is illegible and requires replacement, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/29/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds inside of crude oil tank berm, see attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	02/29/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused sanitary unit on location, see attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	02/29/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Calibration card is outdated. Meter not calibrated annually, see attached photo.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/29/2024
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Pilot is on		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					
					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 242723 Type: WELL API Number: 123-10514 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 03/01/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Tuesday 11/21/2023 at approximately 09:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK McCarty #2 API #123-10514 in Weld County, Colorado.                      While there, I observed that the DCP gas sales meter calibration was out of date, the wellhead sign was illegible, unused equipment on location and weeds inside of the crude oil tank berm. During this inspection the following possible compliance issues were observed: Rule 430.d.(1). with a corrective action date of 2/29/2024, Rule 605.d. with a corrective action date of 2/29/2024 and Rule 606. with a corrective action date of 2/29/2024.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of the inspection report.</p>	petersont	11/21/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403603059	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330832</a>
697008401	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330787">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330787</a>