

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2023

Submitted Date:

11/21/2023

Document Number:

701103857**FIELD INSPECTION FORM**Loc ID 312962 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS INCAddress: 13635 E 104TH AVENUE STE 400City: COMMERCE CITY State: CO Zip: 80022**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wcciassistant@gmail.com	
Lawton, Lisa	(970) 846-4639	lisa@beemanoil.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223046	WELL	PR	02/11/1980	GW	081-06408	ELK SPRINGS UNIT 1	PR

**General Comment:**

Flowline integrity inspection

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Open ended unused 2" flowline riser at well head.		
Corrective Action:	Comply with Rule 606 Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. Immediately within 24 hours comply with OOSLAT requirements per Rule 1101.a.(3).C. (isolate and tag)	Date:	12/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 223046 Type: WELL API Number: 081-06408 Status: PR Insp. Status: PR**Flowline**

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type:                      Size: 2"                      Material: Carbon Steel  
Variance:                      Age:                      Contents:

Integrity Summary

Failures:                      Spills:                      Repairs Made:  
Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☒ 1103. Abandonment

Comment: Open ended unused 2" flowline riser at well head.

Corrective Action:                      Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403603677	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331309">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331309</a>
701103858	Flowline integrity inspection 701103857 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331132">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331132</a>