

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2023

Submitted Date:

11/21/2023

Document Number:

713300310

**FIELD INSPECTION FORM**Loc ID 318409 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
,		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241248	WELL	PR	01/01/2022	OW	123-09036	MATHISEN UNIT A 2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	concrete pumping unit support pad		
Corrective Action:	Comply with Rule 606	Date:	09/07/2023

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	pipe well head guard		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241248 Type: WELL API Number: 123-09036 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, well appeared to be shut in at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
 On Tuesday 11-21-2023 at approximately 11:00, I, Inspector Michael Kester, conducted an on-site reinspection as per Doc # 713300038.  
 Location: Mathisen Unit A 2  
 Operator: KPK  
 API# 123-09036  
 County: Weld  
 While there, I observed producing well site.  
 At time of inspection it does not appear corrective actions from previous inspection have been address.  
 Unused equipment, Rule 606, corrective action 9-7-2023, photo 1 & 2  
 Weather conditions: sunny and dry  
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of inspection report.

This inspection does not nullify any orders or NOAV from the ECMC  
 This is a continuing education inspection

kesterm

11/21/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403603970	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331741">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331741</a>
713300311	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331740</a>