

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2023

Submitted Date:

12/05/2023

Document Number:

713300320

FIELD INSPECTION FORMLoc ID 332996 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
,		randy.silver@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Revas, Robbie		robbie.revas@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248440	WELL	SI	06/01/2020	GW	123-16238	JOHNSON 32-30	PA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	electric diconnect panel, not being used, condicider as unuse equipment, well has been P&A		
Corrective Action:	Comply with Rule 606		Date: 05/02/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 248440 Type: WELL API Number: 123-16238 Status: SI Insp. Status: PA**Workover**Comment: KPK rig 12 on site, spoke with Rick R. moring pressure at 40 psi, tring to wash out behind casing before pumping any more cenment,Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday, 12-4-2023 at approximately 11:00, I, Inspector Michael Kester, conducted an on-site inspection and follow up inspection as per Doc 702401836</p> <p>Location: Johnson 32-30</p> <p>Operator: KPK</p> <p>API#: 123-16238</p> <p>County: Weld</p> <p>While there, I observed well site with workover rig on a reentry.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment, Electrical disconnect panel, corrective action date 5-2-2023, photo 3</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report. Daily rig report be attached.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p> <p>This is a continuing education inspection</p>	kesterm	12/04/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300321	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6344512
713300328	rig report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6344513