

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2023

Submitted Date:

12/04/2023

Document Number:

690011863**FIELD INSPECTION FORM**Loc ID 327226 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246549	WELL	SI	10/01/2020	GW	123-14346	HSR-TUCK 10-24	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	DEBRIS	
Comment:	Weed debris at wellhead.	
Corrective Action:	Comply with 606	Date: 12/11/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:		
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 437520				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date: <div></div>
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date: <div></div>
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date: <div></div>

**Inspected Facilities**Facility ID: 246549 Type: WELL API Number: 123-14346 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well not connected with flow line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/21/2023 Annual Brhd Completed? \_\_\_\_\_Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Corrective action inspection. Weed debris at wellhead.</u>	carlilec	12/04/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403613795	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6342636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6342636</a>
690011864	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6342580">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6342580</a>