

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2023

Submitted Date:

12/04/2023

Document Number:

713300326

FIELD INSPECTION FORMLoc ID 328576 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		randy.silver@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248360	WELL	PR	08/01/2019	OW	123-16158	ANDERSON 22-32	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	debris, DEAD overgrown vegetation	
Corrective Action:	Comply with Rule 606	Date: 12/11/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	safety guards	
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	chain link with wire	
Corrective Action:		Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electrical motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical disconnect panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipe to surface		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 248360 Type: WELL API Number: 123-16158 Status: PR Insp. Status: PR

Producing Well

Comment: PR, well appeared to be shut in at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/10/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On Monday, 12-4-2023 at approximately 14:00, I, Inspector Michael Kester, conducted an on-site inspection.
 Location: Anderson 22-32
 Operator: KPK
 API#: 123-16158
 County: Weld
 While there, I observed well site with pumping unit
 During this inspection the following possible compliance issues were observed:
 Debris, DEAD weeds, Rule 606, corrective action date 12-11-2023
 Weather conditions: sunny and dry
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.
 This is a summary of inspection report.

This inspection does not nullify any orders or NOAV from the ECMC
 This is a continuing education inspection

kesterm

12/04/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403614627	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6344542
713300327	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6344515