

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2023

Submitted Date:

12/05/2023

Document Number:

713300347

FIELD INSPECTION FORM

Loc ID 318531 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , KPK | | cogcc@kpk.com | All Inspections |
| , | | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 241514 | WELL | PR | 08/01/2023 | OW | 123-09303 | COSSLETT 2 | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| | Type WELLHEAD | | |
| Comment: | Faded unreadable Sign not posted or information inaccurate at well | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 01/05/2024 |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 95%;" type="text"/> |
| Corrective Action: | <input style="width: 95%;" type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------------|-------|--|
| | Type PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | corrective date |
|---------------------------|-------------------|-------|--|--|-----------------|
| Type: Pump Jack | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Prime Mover | # 1 | | | | |
| Comment: | electric motor | | | | |
| Corrective Action: | | Date: | | | |
| Type: Ancillary equipment | # 2 | | | | |
| Comment: | electrical panels | | | | |
| Corrective Action: | | Date: | | | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | piped to surface | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|----------|--|--|--|
| Type | | | |
| Comment: | | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241514 Type: WELL API Number: 123-09303 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 09/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>ECMC Inspection Report Summary On Tuesday, 12-5-2023 at approximately 15:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Cosslett 2 Operator: KPK API#: 123-09303 County: Weld While there, I observed well site with pumping unit with production equipment. During this inspection the following possible compliance issues were observed: Sign, Rule 605d, corrective action date 1-5-2024 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p> | kesterm | 12/05/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403615753 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6346711 |
| 713300348 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6346699 |