

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2023

Submitted Date:

12/07/2023

Document Number:

696305479

FIELD INSPECTION FORM

Loc ID 431418 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431412	WELL	SI	10/01/2022	OW	123-36597	State Antelope 34-12-1XRLNB	SI
431417	WELL	PR	06/01/2021	OW	123-36599	State Antelope 44-41-12HNB	PR
465969	WELL	PR	06/24/2021	OW	123-50275	State Antelope J14-F11-12HNB	PR
465970	WELL	PR	06/24/2021	OW	123-50276	State Antelope O24-K21-12HNB	PR
465971	WELL	PR	06/24/2021	OW	123-50277	State Antelope T34-P31-12HNB	PR
465972	WELL	PR	06/24/2021	OW	123-50278	State Antelope Y-U-12HNB	PR
465973	WELL	PR	06/24/2021	OW	123-50279	State Antelope E14-12-1XRLNB	PR
465974	WELL	PR	06/24/2021	OW	123-50280	State Antelope T-44-P41-12HNB	PR
465975	WELL	PR	06/24/2021	OW	123-50281	State Antelope O34-K31-12HNB	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x9)		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		

Comment:	Second Separator from the East is open to Atmosphere. See photos		Date:	12/22/2023
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.			
Type: Bradenhead	# 9			
Comment:	Appear to be plumbed to surface			
Corrective Action:			Date:	
Type: Plunger Lift	# 9			
Comment:				
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Line Heater			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		40.408750,-104.267670
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	431412	Type:	WELL	API Number:	123-36597	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____					
Comment:		SI							
Corrective Action:		_____						Date: _____	
Facility ID:	431417	Type:	WELL	API Number:	123-36599	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465969	Type:	WELL	API Number:	123-50275	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465970	Type:	WELL	API Number:	123-50276	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465971	Type:	WELL	API Number:	123-50277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465972	Type:	WELL	API Number:	123-50278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465973	Type:	WELL	API Number:	123-50279	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:		_____						Date: _____	
Facility ID:	465974	Type:	WELL	API Number:	123-50280	Status:	PR	Insp. Status:	PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 465975 Type: WELL API Number: 123-50281 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. East Separator is open to Atomsphere	petrie	12/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403618701	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349674
696305480	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349632