

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2023

Submitted Date:

12/07/2023

Document Number:

713300366

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 318370 _____ Kester, Michael _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
 Name of Operator: KP KAUFFMAN COMPANY INC _____
 Address: 1700 LINCOLN ST STE 4550 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80203 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 _____ Number of Comments
 1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241182	WELL	SI	09/01/2023	GW	123-08970	CARL A MILLER B 8	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	NO sign on site, Sign not posted or information inaccurate at well		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/08/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: safety guards

Corrective Action: _____ Date: _____

Type OTHER

Comment: electrical disconnect, metal panels

Corrective Action: _____ Date: _____

Equipment:

corrective date

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: electric motor			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: electrical disconnect			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: pipe to surface			
Corrective Action:		Date:	

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241182 Type: WELL API Number: 123-08970 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: valves appeared closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday, 12-7-2023 at approximately 9:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Carl A Miller B8 Operator: KPK API#: 123-08970 County: Weld While there, I observed well site with pumping unit. During this inspection the following possible compliance issues were observed: Sign, Rule 605d, corrective action date 1-8-2024 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	12/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403618703	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349678
713300367	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349655