

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: good

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Electric Motor removed, Pumping Unit unused equipment

Corrective Action: Comply with Rule 606

Date: 01/08/2024

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: safety guards

Corrective Action:

Date:

Equipment:

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: piped to surface

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: electrical panel

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: REMOVED

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239705 Type: WELL API Number: 123-07493 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: valves appeared closed at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday, 12-7-2023 at approximately 12:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Donald E Miller ET AL B1 Operator: KPK API#: 123-07493 County: Weld While there, I observed well site with pumping unit. During this inspection the following possible compliance issues were observed: Unused Equipment, Rule 606, corrective action date 1-8-2024 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	12/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403618705	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349682
713300379	Site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349661