

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2024

Submitted Date:

01/09/2024

Document Number:

702402814

FIELD INSPECTION FORM

Loc ID 311318 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241484	WELL	PR	03/01/2020	GW	123-09273	GUILDNER 2	SI

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Dead vegetation by the ancillary equipment and around the pump jack		
Corrective Action:	comply with rule 606		Date: <u>01/17/2024</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:			Date:
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Fabricated round stock and barb wire		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover			# 1
Comment:			electric motor
Corrective Action:			Date:
Type: Bradenhead			# 1
Comment:			appears plumbed to surface
Corrective Action:			Date:
Type: Ancillary equipment			# 1
Comment:			electric panel, meter box and transformers
Corrective Action:			Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241484 Type: WELL API Number: 123-09273 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, all valves are closed and electric panel switch is off.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 1-9-2024 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID # 311318 Well Name: Guildner 2 API # 05-123-09273 County: Weld Weather: Cloudy/ clear and cold Location: Dry While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 606 housekeeping: CA date 1-17-2024 See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	01/09/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403649517	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387077
702402815	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387070