

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2024

Submitted Date:

01/17/2024

Document Number:

702402914**FIELD INSPECTION FORM**Loc ID 305090 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 274043 | WELL | TA | 02/26/2019 | GW | 123-22431 | PARAGON FARMS 42-25 | TA |

General Comment:

Location

| | | | |
|--------------------|---|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access rd. overrun with tall dead vegetation. | | |
| Corrective Action | Comply with Rule 606 | Date: | 01/25/2024 |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|-------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | Date: | | |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Wellsite is overrun with tall dead vegetation | | |
| Corrective Action: | Comply with Rule 606 | Date: | 01/25/2024 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Ag panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | exposed at surface | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 274043 | Type: | WELL | API Number: | 123-22431 | Status: | TA | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: | | | | | | | | | |
| Comment: TA Form 04-(TA)-00 Doc # 402977387 & Form 06A Doc # 403108165 | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: 12/20/2023 | | | | | | | | | |
| Annual Brhd Completed? Yes | | | | | | | | | |
| Last Brhd Test Results | | | | | | | | | |
| Initial Surf Csg Pressure: 0 | | | | | | | | | |
| Fluid Type: NONE | | | | | | | | | |
| End Surf Csg Pressure: 0 | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Wednesday 1-17-2024 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 702402752.</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name:</p> <p>Location ID # 305090</p> <p>Well Name: Paragon Farms 42-25</p> <p>API # 05-123-22431</p> <p>County: Weld</p> <p>Weather: Mostly sunny.</p> <p>Location: Snow covered.</p> <p>While there, I observed a wellsite, TA at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>606 Housekeeping: CA date 1-25-2024.</p> <p>I observed the compliance issue 204 Access: has been addressed.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> | revasr | 01/17/2024 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403657953 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396249 |
| 702402915 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396238 |