

Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Energy & Carbon Management Commission
40.30666, -104.64865, 1427.7m, 353°
Feb 5, 2024 12:31:45



Energy & Carbon Management Commission
40.30706, -104.64864, 1433.5m, 34°
Feb 5, 2024 13:02:21

Photo 1: Location from entrance

Photo 2: Centralized Tank Battery



Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Photo 3: Equipment



Photo 4: Unused Riser

Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Energy & Carbon Management Commission
40.30742, -104.64781, 1422.7m, 4°
Feb 5, 2024 13:00:53

Photo 5: Unused riser



Energy & Carbon Management Commission
40.30677, -104.64715, 1425.0m, 115°
Feb 5, 2024 12:53:40

Photo 6: Location of wellheads

Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Photo 9: Wellhead Sign



Photo 10: Wellhead



Inspection Photos
Location Name: Francis Arens 5-6-15, 34-15
Location ID: 332680



Energy & Carbon Management Commission
40.30666, -104.64677, 1421.8m, 350°
Feb 5, 2024 12:55:04

Photo 11: Weeds