

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	Tall dead vegetation along access rd. and around location ROW		
Corrective Action:	Comply with rule 606	Date:	02/07/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date
Ancillary equipment	# 1	electric panel, meter box and transformers.		
Prime Mover	# 1	electric motor		
Pump Jack	# 1			
Bradenhead	# 1	plumbed to surface		

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242357 Type: WELL API Number: 123-10148 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, valves are closed and electric panel is shut off.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/16/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 1-30-2024 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID #311333 Well Name: Energy Minerals Unit A1 API # 05-123-10148 County: Weld Weather: Sunny, clear. Location: Dry. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issue: 606 House Keeping: CA date 1-7-2024 See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	01/30/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403671680	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6412862
702403046	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6412849