

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2024

Submitted Date:

02/05/2024

Document Number:

690012252**FIELD INSPECTION FORM**Loc ID 336458 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | Inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|-----------------------------------|-------------|
| 482249 | TANK BATTERY | AC | 05/31/2022 | | - | Devore-63N66W 34NENE Tank Battery | AO |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | "Sign not legible Sign not updated to reflect current operator" Capacity and National Fire Protection Association labels on produced water tanks. See photo # 6 | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 03/06/2024 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 7 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 11 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 4 | 200 BBLs | PBV FIBERGLASS | | , |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shared with condensate tanks. | | | |
| Corrective Action: | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----|----------|-----------|---------|-----------------------|
| CONDENSATE | 18 | 400 BBLs | STEEL AST | | 40.187960,-104.756070 |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------------------|
| Type | Ignitor/Combustor |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|---|---------|----|---------------|----|
| Facility ID: | 482249 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | AO |

| COGCC Comments | | |
|---|----------|------------|
| Comment | User | Date |
| Corrective action inspection. Produced water tanks need capacity and National Fire Protection Associate labels installed. | carlilec | 02/05/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403676992 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419077 |
| 690012253 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419062 |