

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/26/2024

Document Number:

696305857**FIELD INSPECTION FORM**Loc ID 310627 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296229	WELL	TA	01/01/2022	OW	123-26704	Wells Ranch USX AE 21-12	TA

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Weeds on Access Road; see photos			
Corrective Action	Comply with Rule 606 and 1003.f			Date: 02/09/2024
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Weeds and Tumbleweeds at Wellsite; see photos			
Corrective Action:	Comply with Rules 606 and 1003.f.			Date: 02/09/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Panels			
Corrective Action:				Date:
Equipment:				
			corrective date	
Type: Other	# 1			
Comment:	TA Wellhead			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Unused Pumping Unit, Gas Engine and Engine House			
Corrective Action:	Comply with Rule 606			Date: 03/29/2024
Venting:				
Yes/No				

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 296229

Type: WELL

API Number: 123-26704

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: TA - 01.01.2022.
MIT - 08.04.2020
Form 6A 403118488 dated 08.16.2022 with a Plug Due Date of 12.31.2030

Corrective Action:

Date:

COGCC Comments		
Comment	User	Date
Routine Field Inspection. Weeds and Tumbleweeds on Lease Road and at Wellsite. Unused Pumping Unit	petrie	01/26/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403668469	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408966
696305858	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408962