

Final Reclamation Inspection

March 6th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 333494

Inspection Document #: 714000533

La Plata County, CO

Township: NWSE 32 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 32-2, 2A
Location ID: 333494



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



Photo 2. View of the persisting gully erosion and inadequate/failing storm water BMP issues observed in the southern interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08246, 09383

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the persisting gully erosion and inadequate/failing storm water BMP issues observed in the western interim reclamation area.

API #: 067-08246, 09383

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



3/6/24

+37.144696,-107.955195

22° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. view of erosion impacting secondary containment around tanks.

API #: 067-08246, 09383

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



3/6/24

+37.144793,-107.954769

155° SE



3/6/24

+37.144791,-107.954896

175° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Rutting observed in the center of the location. Additional stabilization is needed to minimize site degradation.

API #: 067-08246, 09383

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



3/6/24

+37.144775,-107.955257

249° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of gambel oak and rabbitbrush.

API #: 067-08246, 09383