

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Location Entrance – Photo #09737



Wellheads/Chem Tank – Photo #09738



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Wellhead – Photo #09741



Wellhead – Photo #09742



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Separators – Photo #09743



Separators – Photo #09744





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Tank Battery – Photo #09746



ECD – Photo #09745

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Stored Equipment – Photo #09747



Open-Ended Load Line – Photo #09748



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



Lack of Stabilization – Photo #09749



Lack of Stabilization – Photo #09750

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 3/7/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #09751