

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 28 6S92W



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9416 Stockpiled soils with no BMP's

Photo # 9417 Stockpiled soils with no BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9418 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 9419 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9420 Lack of stabilization/compaction/insufficient tracking BMP's

Photo # 9421 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9422 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 9423 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9424 Lack of stabilization/compaction/insufficient tracking BMP's

Photo # 9425 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9426 Lack of stabilization/compaction/insufficient tracking BMP's

Photo # 9427 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY # 3 Pad
Location ID: 335147



Photo # 9428 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 9429 Lack of stabilization/compaction/insufficient tracking BMP's