

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEFT HAND FEDERAL A Pad

Location #: 335543



Photo # 9832 From entrance to location




Photo # 9833 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEFT HAND FEDERAL A Pad

Location #: 335543



Photo # 9834 Location



Photo # 9835 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEFT HAND FEDERAL A Pad

Location #: 335543



Photo # 9836 Location



Photo # 9837 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEFT HAND FEDERAL A Pad

Location #: 335543



Photo # 9838 PRV vent line for tank burner does not comply with CECMC pressure safety device rules & also terminates in an unsafe manner



Photo # 9839 PRV vent line for tank burner does not comply with CECMC pressure safety device rules & also terminates in an unsafe manner

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEFT HAND FEDERAL A Pad

Location #: 335543



**Photo # 9840 Wellhead cellar cover not properly installed
/wildlife & personnel hazard**