

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2024

Submitted Date:

03/13/2024

Document Number:

698706057

FIELD INSPECTION FORMLoc ID 421814 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, PDC		cogccinspection@pdce.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421819	WELL	SI	04/01/2022	OW	123-33076	OPDYKE USX I 03-17	SI

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris in wellhead area needs to be cut & removed		
Corrective Action:	Statewide unnecessary equipment, weeds, waste, and trash requirements Comply with rule 606	Date:	03/22/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 421819 Type: WELL API Number: 123-33076 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI
Flowline valve is closed

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 01/19/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On 3/13/24 at approximately 10:20 am, I, Inspector Abe Serna, conducted an on-site inspection. Location: Opdyke USX I 3-17 Operator: PDC Energy API#: 123-33076 County: Weld While there, I observed a SI Well During this inspection the following possible compliance issues were observed: Statewide unnecessary equipment, weeds, waste, and trash requirements Rule 606 Action Date) See attached photo #. 2 Weather conditions: Cloudy A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report. Any corrective actions from previous inspections that have not been addressed are still applicable	sernaa	03/13/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403718461	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465427
698706058	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465404