

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2024

Submitted Date:

03/19/2024

Document Number:

699108428

FIELD INSPECTION FORM

Loc ID 413215 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|----------------|-------------|
| 413215 | LOCATION | AC | 05/04/2022 | | - | BARTON C 15-29 | SI |

General Comment:

[This is an inspection on the tank battery.](#)

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-----------------|-------|-------|
| Emergency Contact Number: | | | |
| Comment: | <u>Adequate</u> | | |
| Corrective Action: | | Date: | _____ |

| Good Housekeeping: | | | |
|---------------------------|--|--|-------------------------|
| Type | OTHER | | |
| Comment: | Stained soil by the flowline and balon valve that appears to be leaking, needs to be removed. See attached photos. | | |
| Corrective Action: | "Properly dispose of oily waste in accordance with 905.e." | | Date: <u>04/05/2024</u> |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|-----------------------------------|--|-------|-------------------------|
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: | # | | |
| Comment: | Balon Valve on west side of production takes appears to be leaking and needs fixed or replaced. See attached photos. | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | | Date: <u>04/05/2024</u> |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|--------------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) 48 BBLs | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 2 | OTHER | BV CONCRETE | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|--------------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) 60 BBLs | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 3 | 300 BBLs | STEEL AST | | 40.325300,-104.545700 |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 413215 Type: LOCATION API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary On Monday, 3/19/2024 at approximately 0920, I, Inspector Adam Burns, conducted an on-site inspection. Location: Barton C 15-29 Tank Battery Operator: Chevron Location ID: 413215 County: Weld While there, I observed a shut in tank battery During this inspection the following possible compliance issues were observed: Balon Valve on west side of production takes appears to be leaking and needs fixed or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a Corrective Action date of 4/5/24 Stained soil by the flowline and balon valve that appears to be leaking, needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 4/5/24 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable</p> | burnsa | 03/19/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403724925 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6473326 |
| 699108429 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6473320 |