

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

713300710

FIELD INSPECTION FORM

Loc ID 317757 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|--------------------------|---------------------------------|
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 239927 | WELL | SI | 05/01/2021 | OW | 123-07715 | DOVERSBERGER, EUGENE 2 | SI |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | good, only fastened with one screw | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|-------|--|
| Type | PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--------------------------------|-------|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | piped to surface | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | electric and automation panels | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|----------|--|--|
| Type | | |
| Comment: | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 239927 Type: WELL API Number: 123-07715 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/18/2024

BradenHead

Date of Last Brhd Test: 05/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p><u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site inspection.</u> <u>Location: Doversbeger Eugene 2</u> <u>Operator: KPK</u> <u>API#: 123-07715</u> <u>County: Weld</u> <u>While there, I observed well site with pumping unit,</u> <u>During this inspection, the following possible compliance issues were observed:</u> <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-18-2024</u></p> <p><u>Weather conditions: sunny and dry</u> <u>A follow up on this site inspection needs to be conducted to ensure the</u> <u>Compliance issues have been corrected to comply with ECMC rules.</u> <u>This is a summary of inspection report.</u></p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u> <u>This is a continuing education inspection</u></p> | kesterm | 03/18/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403723721 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472329 |
| 713300711 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472319 |