
Triple Combo Main Pass
Triple Combo Repeat Pass
Gamma Ray Only Pass
Caliper Only Pass
Density Porosity
Neutron Porosity
Gamma Ray
Caliper
Bit Size
Resistivity
Deep Resistivity
Medium Resistivity
Shallow Resistivity
Photoelectric Factor
Delta Rho
Rhomaa
Pe
Drho
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Deep Resistivity (ohmm)
Medium Resistivity (ohmm)
Shallow Resistivity (ohmm)
Photoelectric Factor (b/e)
Delta Rho (g/cc)
Rhomaa (g/cc)
Density Porosity (dec)
Neutron Porosity (dec)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Deep Resistivity (ohmm)
Medium Resistivity (ohmm)
Shallow Resistivity (ohmm)
Photoelectric Factor (b/e)
Delta Rho (g/cc)
Rhomaa (g/cc)
Density Porosity (dec)
Neutron Porosity (dec)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Deep Resistivity (ohmm)
Medium Resistivity (ohmm)
Shallow Resistivity (ohmm)
Photoelectric Factor (b/e)
Delta Rho (g/cc)
Rhomaa (g/cc)
Density Porosity (dec)
Neutron Porosity (dec)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Deep Resistivity (ohmm)
Medium Resistivity (ohmm)
Shallow Resistivity (ohmm)
Photoelectric Factor (b/e)
Delta Rho (g/cc)
Rhomaa (g/cc)
Density Porosity (dec)
Neutron Porosity (dec)