5

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 388220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

DEC 16 2010

OUR INVOICE

198708

(BOH 91036)

Date 12-5-10	Well Owner PDC	Well No. 22BD	Lease CHESNUT
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-5)			For Office Use Only
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Ft. 699 To
Surface 8 5/8" CSG - 24#		Bottom of Surface	Ft. 689 To
Plug		Plug Landed @ 643 Ft.	Time On 2015
Production		Pipe Landed @ 689 Ft.	~~Time Off~~ PLUG DOWN 2030

Reference No.	Description	Qty.	Mea.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	490	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele # Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				

MIX RATE 4 BPM	SLURRY VOL 1.18	FT³/SK			
DISP RATE 5 BPM	SLURRY WT 15.2	PPG			
PLUG LANDED @ 600 PSI	TOTAL SLURRY VOL	103	BBL	CEMENT	

Remarks:	Tax Reference Code	Sub Total
PREFLUSH W/ 20 BBL H20		
DISPLACE W/ 40.5 BBL H20	State CO 2.9 %	Tax
CIRCULATE 5 BBL CEMENT	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1202		Pump Truck		18		
1214		Bulk Truck		18		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review

Delivered By JOE, TRAVIS, KELLY, EVAN

Received By

Customer or His Agent