

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct Intermediate casing test.

Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 10084	2. Name of Operator: <u>WATER RESOURCES</u>	3. BLM Lease No: <u>N/A</u>
4. API Number: <u>05-071-06936</u>	5. Multiple completion? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
6. Well Name: <u>LA & Low</u>	Number: <u>43-34</u>	
7. Location (Qtr, Sec, Twp, Rng, Meridian): <u>NE/SE, SEC. 34 - T. 33S - R. 65W</u>		
8. County: <u>LAS ANIMAS</u>	9. Field Name: <u>WATERBURY RIVER</u>	
10. Minerals: <input checked="" type="checkbox"/> Fee <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian		

14. STEP 1: EXISTING PRESSURES

Record all pressures as found	Tubing: <u>0</u>	Prod. Casing: <u>5</u>	Intermediate Casing: <u>0</u>	Surface Casing: <u>0</u>
	Fracture: <u>0</u>	Fracture: <u>0</u>		

16. STEP 3: BRADENHEAD TEST

Buried valve? ☐ Yes ☒ No Confirmed open? ☐ Yes ☒ No

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures). Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below:

O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H₂O; M = Mud; W = Whelpet; S = Surges; G = Gas

BRADENHEAD SAMPLE TAKEN?

☐ Yes ☒ No ☐ Gas ☐ LiquidCharacter of Bradenhead fluid: ☐ Clear ☐ Fresh☐ Sulfur ☐ Salty ☐ Black☐ Other: (describe)

Sample cylinder number:

Elapsed Time (min:sec)	Fracture	Tubing	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow
00:			5		0
05:					
10:					
15:					
20:					
25:					
30:					

Note Instantaneous Bradenhead PSIG at end of test: >

17. STEP 4: INTERMEDIATE CASING TEST

Buried valve? ☐ Yes ☒ No Confirmed open? ☐ Yes ☒ No

With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below:

O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H₂O; M = Mud; W = Whelpet; S = Surges; G = Gas

INTERMEDIATE SAMPLE TAKEN?

☐ Yes ☐ No ☐ Gas ☐ LiquidCharacter of intermediate fluid: ☐ Clear ☐ Fresh☐ Sulfur ☐ Salty ☐ Black☐ Other: (describe)

Sample cylinder number:

Elapsed Time (min:sec)	Fracture	Tubing	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow
00:					
05:					220
10:					240
15:					240
20:					
25:					
30:					

Note Instantaneous Intermediate Casing PSIG at end of test: >

18. Comments: Water going to the pit -

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: Isabel Cardeñas Title: Flackland II Phone: 719 846-7898Signed: Isabel Cardeñas Title: _____ Date: 5-27-09

WITNESSED BY: _____ Title: _____ Agency: _____