




02469076

09-103-05692
Location # 314435

REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

To: District Engineer ~~USGS~~ BLM - Fluid Minerals Branch, Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill Discharge Blowout Accident Fire or Explosion
- 2. BBLS Discharged: 400 BBLS Lost: 400
- 3. Contained on location: Yes No
- 4. Date and time of event: 1/10/88 3:30 PM
- 5. Date and time reported to U.S.G.S.: _____
- 6. Location of event: UP 2-20 SW SE Sec. 20 T2N, R102W
- 7. Specific nature and cause of event
Gathering line leak
- 8. Describe resultant damage:
- 9. Time required for control of event: 15 min.
- 10. Action taken to control and contain:
Water ran into catch pond 20 yds. from leak, picked up and hauled to Fee 10 pit.
- 11. Action taken to prevent recurrence:
Repair section of 16" line and return to operation.
- 12. Cause of death:
N/A



- 13. Other agencies notified:
Colorado Department of Health, Air Quality Control, Denver, Co.
Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only
- 14. Other pertinent information:

Signature T. L. Hurst 1/13/88 Date _____
Title Unit Area Supervisor