



photo 1: Facing toward the wellhead.



photo 2: Pit at the north side of the location. No free board marker was noticed.



photo 3: Facing along the west side of the location. Guy line anchor are not marked.



photo 4: Facing toward the south side of the location.