

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/09/2017

Submitted Date:

11/09/2017

Document Number:

679700667**FIELD INSPECTION FORM**

Loc ID 307205 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	
Axelson, John		john.axelson@state.co.us	
Warner, Ryan	970-669-6308	magpieoil@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453020	TANK BATTERY	AC			-	Bunker 2a & 7	EI

**General Comment:**

COGCC inspection of Bunker 2a &amp; 7 Tank Battery

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Containment berms are wearing, restore integrity and capacity of secondary containment			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 12/09/2017

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Spill/Remediation:**

Comment: Remediation #4164 for pit closure remains unresolved.

Corrective Action: Submit documentation to COGCC regarding disposition of soil from pit closure and sample results from pit closure

Date: 01/09/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401455070	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298811">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298811</a>
679700669	Inspection Photos 11/9/2017	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298809">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298809</a>
679700670	Approved Form 27 Remediation 4164	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298810">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298810</a>