

co_dnr_div_ogcc_300_rgb_ltrhd_v3

Spill ID# 457384
Doc# 2303012
Date: 09/19/2018

P [303.894.2100](tel:303.894.2100) x5138 | F [303.894.2109](tel:303.894.2109)

[1120 Lincoln Street, Suite 801, Denver, CO 80203](https://www.colorado.gov/cogcc)

| alex.fischer@state.co.us www.colorado.gov/cogcc

----- Forwarded message -----

From: **Wayne Bankert** <wbankert@laramie-energy.com>

Date: Wed, Sep 19, 2018 at 9:15 PM

Subject: HDU 9-41D 10" Open ended in relation to "Frac" Pit

To: Luke Cody <lcody@laramie-energy.com>, Eric Lane <elane@laramie-energy.com>, Lorne Prescott <lprescott@laramie-energy.com>, Stuart Hall <shall@entradainc.com>, Chris Clark <cclark@laramie-energy.com>

Cc: Fischer - DNR, Alex <alex.fischer@state.co.us>, Steven Arauza - DNR <steven.arauza@state.co.us>, Byers, James <jbyers@blm.gov>, Woolley, Carmia (cwoolley@blm.gov) <cwoolley@blm.gov>

FYI,

Using historical photos from Jim Byers, google earth, and the leak Lat/long, this is what I came up with for distance between the 10"

and the pit edge.

Thanks

Wayne P. Bankert

Piceance Reg. & Env. Manager

Laramie Energy, LLC

[760 Horizon Drive Suite 101](https://www.laramie-energy.com)

[Grand Junction, CO 81506](https://www.laramie-energy.com)

O: 970-812-5310

M: 970-985-5383

wbankert@laramie-energy.com

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado

co_dnr_div_ogcc_300_rgb_ltrhd_v3

P 303.894.2100 x5138 | F 303.894.2109 | C 303.501.3900

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us | www.colorado.gov/cogcc

2 attachments



HDU 9-41D Pit and Leak.jpg
270K



image003.jpg
5K