

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401832304

Date Received:

11/08/2018

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 4 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Wentzel, Dougo

dougo.wentzel@state.co.us

Colby, Lou

lou.colby@state.co.us

Knudson, Dwayne

970-456-3335

dknudson@ursaresources.com

Longworth, Mike

mike.longworth@state.co.us

Pesicka, Conor

conor.pesicka@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 692700002

Inspection Date: 10/30/2018

FIR Submit Date: 11/02/2018

FIR Status: _____

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 1600 BROADWAY ST STE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 440634

Location Name: B & V PAD Number: _____ County: _____

Qtrqr: NWS Sec: 7 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.450245 Longitude: -108.047080

FACILITY - API Number: 05-045- -00 Facility ID: 440634

Facility Name: B & V PAD Number: _____

Qtrqr: NWS Sec: 7 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.450245 Longitude: -108.047080

CORRECTIVE ACTIONS:

1 CA# 120141

Corrective Action: Remove all equipment no longer needed for the production or completion of wells located on Loc # 440634.

Date: 12/03/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: The FlexFlow line mentioned in the inspection is not on the B&V pad. Ursa has attempted to remove this line on two occasions after the road crossing by the city was completed (this operation prevented removal), once the equipment and personnel from FlexFlow were onsite and were shut down due to the GarCO fire restrictions. This FlexFlow material requires a very specific removal process, the company has been one month out to schedule removal. Ursa continues to pursue removal now that fire restrictions have been lifted but are at the mercy of the contractor but are hopeful to get removed before the end of the year.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Shaun Kellerby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed: _____

Title: Environmental Manager

Date: 11/8/2018 12:16:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files