

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type			
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	Square tubing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	Gas powered motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1	
Comment:	Sight glass on seperator is broke and gas is leaking	
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date: 11/15/2018
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.537025,-104.329588
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201916 Type: WELL API Number: 001-07320 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection sight glass on heated seperator was broke and gas was venting of brass valve. Called emergency number spoke HRM forman in whyoming he was going to have someone call me back from colorado. Did not receive call back at time of inspection.	silverr	11/15/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400585	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647273