

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401827967  
Date Received:  
11/06/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 4 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Knudson, Dwayne</u>	<u>970-456-3335</u>	<u>dknudson@ursaresources.com</u>
<u>Wentzel, Dougo</u>		<u>dougo.wentzel@state.co.us</u>
<u>Longworth, Mike</u>		<u>mike.longworth@state.co.us</u>
<u>Colby, Lou</u>		<u>lou.colby@state.co.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 692700002

Inspection Date: 10/30/2018

FIR Submit Date: 11/02/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 1600 BROADWAY ST STE 2600

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 440634

Location Name: B & V PAD Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: NWS Sec: 7 Twp: 7S Range: 95W Meridian: 6  
W

Latitude: 39.450245 Longitude: -108.047080

### FACILITY - API Number: 05-045- -00 Facility ID: 440634

Facility Name: B & V PAD Number: \_\_\_\_\_

Qtrqtr: NWS Sec: 7 Twp: 7S Range: 95W Meridian: 6  
W

Latitude: 39.450245 Longitude: -108.047080

### CORRECTIVE ACTIONS:

3 ☒ CA# 120143

Corrective Action: Close or mark all holes located around the edge of pad site. Due to the immediate danger created by this condition, a corrective action of 48 hours is specified on this FIR.

Date: 11/05/2018

Response: CA COMPLETED

Date of Completion: 11/02/2018

Operator Comment: Holes identified in inspection were from the sound wall beams. These holes were also identified as a hazard by Ursa personnel and were closed after the date of inspection but before receipt of the inspection report during the reclamation of the pad.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please send to Shaun Kellerby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed: \_\_\_\_\_

Title: Environmental Manager

Date: 11/6/2018 10:37:26 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401827967	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files