

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401919250

Date Received:

01/28/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed

0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685305094

Inspection Date: 07/26/2018

FIR Submit Date: 07/27/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326272

Location Name: RICHARDSON GU E-N35N8W Number: 35SWNW County: LA PLATA

Qtrqr: SWN Sec: 35 Twp: 35N Range: 8W Meridian: N  
W

Latitude: 37.261501 Longitude: -107.719080

FACILITY - API Number: 05-067- -00 Facility ID: 216147

Facility Name: RICHARDSON E Number: 1

Qtrqr: SWN Sec: 35 Twp: 35N Range: 8W Meridian: N  
W

Latitude: 37.261501 Longitude: -107.719080

CORRECTIVE ACTIONS:

1 CA# 117690

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 08/27/2018

Response: CA COMPLETED

Date of Completion: 08/13/2018

Operator  
Comment:

Action Completed: The diversion ditch/berm at the base of the slope was rebuilt and a rock run-down was built from its south outlet down to the access road bar ditch. Rebuilt two rock run-downs on the east fill slope. Repaired access road erosion, reseeded all disturbed areas and removed miscellaneous trash and debris. See attached photos

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Action Completed: The diversion ditch/berm at the base of the slope was rebuilt and a rock run-down was built from its south outlet down to the access road bar ditch. Rebuilt two rock run-downs on the east fill slope. Repaired access road erosion, reseeded all disturbed areas and removed miscellaneous trash and debris. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 1/28/2019 7:29:11 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

401919256	CA and Comment Completion photos
-----------	----------------------------------

Total Attach: 1 Files