

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2019

Submitted Date:

02/08/2019

Document Number:

688000256**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 312301 YOUNG, ROB 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	All Inspections

General Comment:

Environmental inspection related to Rem #12431, former oil skim pit and production pit (110639) closure. Additional hydrocarbon impacted soil requires removal from the south wall of the excavation. Historic hydrocarbon impacted soil in the vicinity of the crude oil loadouts should be removed and disposed along with the oil skim pit excavation soil.

Environmental**Spill/Remediation:**

Comment: Based on field observations, hydrocarbon impacted soil related to the former oil skim pit appears to have been adequately removed (pending laboratory analytical confirmation) with the exception of the south wall.

Corrective Action: Remove additional soil from the south wall and provide confirmation soil sample results on a supplemental eForm 27.

Date: 03/29/2019

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000257	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729076