

GOLDEN EAGLE 28-14 API # 05-071-08749 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401105



PHOTO 1: THE 15 BBL WATER TANK WILL BE PUT IN  
USE TO DRAIN THE FUEL SCRUBBER.

GOLDEN EAGLE 28-14 API # 05-071-08749 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401105



PHOTO 2: THE STAINED SOIL AROUND THE WELL HEAD HAS BEEN CLEANED UP.

GOLDEN EAGLE 28-14 API # 05-071-08749 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401105



PHOTO 3: THE STAINED SOIL AROUND THE ENGINE SKID HAS BEEN CLEANED UP.

GOLDEN EAGLE 28-14 API # 05-071-08749 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401105



PHOTO 4: THE STAINED SOIL AROUND THE LIQUID RING SKID HAS BEEN CLEANED UP.

GOLDEN EAGLE 28-14 API # 05-071-08749 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401105



PHOTO 5: THE STAINED SOIL AROUND THE LIQUID RING SKID HAS BEEN CLEANED UP.