

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID.

Corrective Action:

Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. (THIS IS SECOND WARNING OF IMPACTED SOIL AROUND COMPRESSOR SKID, ENFORCEMENT WILL BE CONSIDERED IF CORRECTIVE ACTION IS NOT ADDRESSED PRIOR TO NEXT INSPECTION).

Date: 12/03/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 277849 Type: WELL API Number: 071-08389 Status: PR Insp. Status: PR

Producing Well

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#695100622, NOT ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. THIS IS THE SECOND WARNING FOR IMPACTED SOIL NEAR COMPRESSOR SKID, ENFORCEMENT WILL BE CONSIDERED IF CORRECTIVE ACTION IS NOT ADDRESSED PRIOR TO NEXT INSPECTION. | beardsit | 11/18/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 695101753 | INSPECTION PHTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991738 |