

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402062074

Date Received:

07/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Pohl, April

505-444-0520

apohl@enduringresources.com

Felix, Andrea

afelix@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900243

Inspection Date: 04/22/2019

FIR Submit Date: 05/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 326660

Location Name: WHEELER-M34N10W Number: 13NWNE County: LA PLATA

Qtrqr: NWNE Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.196938 Longitude: -107.882148

FACILITY - API Number: 05-067- -00 Facility ID: 261590

Facility Name: WHEELER Number: 13-4

Qtrqr: NWNE Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.196938 Longitude: -107.882148

CORRECTIVE ACTIONS:

1 ☒ CA# 124805

Corrective Action: Revegetation is needed in portions of well pad cut and fill slopes that are not stabilized with vegetation. Any portions of the well pad that are not needed for production operations need to be reclaimed.

Date: 05/31/2019

Response: CA COMPLETED

Date of Completion: 07/02/2019

Operator Comment: Hydroseeding completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 124806

Corrective Action: Stormwater and erosion controls including, but not limited to revegetation are needed to stabilize erosion within the project area. Areas needing revegetation (described above) need to be stabilized with erosion controls until vegetation is established and erosion is stabilized. Erosion and stormwater controls need to be selected and installed using good engineering practices such as those recommended by CDOT in their erosion control manuals. Stormwater controls and revegetation need to be monitored and maintained.

Date: 05/31/2019

Response: CA COMPLETED

Date of Completion: 05/28/2019

Operator
Comment:

Stormwater and erosion corrective actions have been completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: APRIL E POHL

Signed: _____

Title: REGULATORY SPECIALIST

Date: 7/8/2019 8:25:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402062074	FIR RESOLUTION SUBMITTED
402083602	Corrective actions photos
402098119	Hydroseeding photo

Total Attach: 3 Files