

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402127068

Date Received:

09/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900462

Inspection Date: 06/19/2019

FIR Submit Date: 07/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 324471

Location Name: FEDERAL-611S90W Number: 35SWNE County: GUNNISON

Qtrqtr: SWNE Sec: 35 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.058950 Longitude: -107.413417

FACILITY - API Number: 05-051- -00 Facility ID: 275738

Facility Name: FEDERAL Number: 11-90-35#1

Qtrqtr: SWNE Sec: 35 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.058950 Longitude: -107.413417

CORRECTIVE ACTIONS:

1 ☒ CA# 126780

Corrective Action: Repair/replace erosion control blanket, additional slope stabilization measures are needed on all well pad cut-slopes.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/28/2019

Operator Comment: Erosion blankets installed in 2017 have a 18-month life span. After 18 months the blankets are designed to decompose - this is what the blankets did this season. They stabilized the slope and allowed some more vegetation to grow. However, the biodegradable blankets have been removed and hydromulch has been added to aid in slope stabilization. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

Photos indicate that temporary slope stabilization measures are installed in response to corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed: _____

Title: Env & Reg Manager

Date: 9/3/2019 11:39:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402127068	FIR RESOLUTION SUBMITTED
402164007	Fed 11-90-35 #1 CA photos

Total Attach: 2 Files