



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Trash on location see pic 1		
Corrective Action:	Comply with 603 f.	Date:	04/16/2020
Type	OTHER		
Comment:	stained soil on location see pic 1		
Corrective Action:	comply with 603 f.	Date:	04/16/2020
Type	OTHER		
Comment:	unused no LOTO riser on location.		
Corrective Action:	Comply with 603 f.	Date:	04/16/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203548 Type: WELL API Number: 001-09108 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 3/16/20 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at Petroshare- API 001-09438 Marlatt 22-22 in Adams County Colorado. While there, I observed Shut in well                      This is a follow up inspection from document # 687400644                      Corrective actions from previous inspection appear to have been addressed.                      During this inspection the following possible compliance issues were observed:                      Trash on location see pic 1                      Comply with 603 f. 4/16/20                      stained soil on location see pic 1                      comply with 603 f.                      unused no LOTO riser on location.                      Comply with 603 f. 4/16/20                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection perception of location may have been distorted due to weather conditions.                      This is a summary of inspection report.</p>	medinaj	03/16/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402345865	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098877</a>
699500972	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098869">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098869</a>