

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/09/2020

Document Number:

699800885**FIELD INSPECTION FORM**Loc ID 334555 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259487	WELL	PR	02/15/2003	GW	077-08728	BUZZARD CREEK 14-1	PR
262734	WELL	PR	12/01/2019	GW	077-08753	BUZZARD CREEK 14-8	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 4/9/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Buzzard Creek /14B Pad, Location #334555 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Both 500 gallon methanol tanks missing operator name and contact number. See photo #0942 with a corrective action date of 6/9/20. Multiple deadman not marked. See photo #0943 and #0949 with a corrective action date of 4/23/20. Multiple holes in tank containment Liner. See photo #0945, #0946 and #0947 with a corrective action date of 4/29/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Both 500 gallon methanol tanks missing operator name and contact number. See photo #0942		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with Name of operator, Operator's emergency contact telephone number. Properly label tanks.		Date: 06/09/2020
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 2		corrective date
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Multiple deadman not marked. See photo #0943 and #0949		
Corrective Action:	All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height. Properly mark deadman.		Date: 04/23/2020
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Multiple holes in tank containment Liner. See photo #0945, #0946 and #0947			
Corrective Action:	Secondary containment devices shall be sufficiently impervious to contain any spilled or released material. Repair tank containment liner.			Date: 04/29/2020

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 259487 Type: WELL API Number: 077-08728 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 262734 Type: WELL API Number: 077-08753 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
		Compaction				
		Culverts				
		Ditches				
Ditches						
Berms						
Compaction						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402367299	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120209
699800886	Photos for Insp. #699800885	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120203