

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Crude Oil	Tank			
Comment:		Crude Oil leaked from Tank, standing oil inside and outside of containment. Run down approximately 140' from containment. Volume unknown at this time		
Corrective Action:		Control and contain spills/releases and clean up per Rule 906.a. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.		Date: <u>05/06/2020</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Inspected FacilitiesFacility ID: 417784 Type: WELL API Number: 123-31744 Status: PA Insp. Status: PA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On Tuesday 05/05/2020 at approximately 14:00. I, Inspector, Erica Petrie, conducted a on-site inspection at Foundation Energy Management. Hillman 9-1 at Location ID #417783 located in Weld County, Colorado</p> <p>While there, I observed: Plugged and Abandoned well.</p> <p>Well has a PA Status as of 03/19/2019. Well had been cut and capped. Final Reclamation has not yet started. 2 Tanks remain on location. 1 labeled Crude Oil, the other tank was not Labeled.</p> <p>Crude Oil Tank released fluid of unknown volume, fluid is in and outside of Containment. Containment integrity was compromised.</p> <p>I called the 24 Hour Emergency Number and spoke with Sara about the situation. She said she would pass on the information to the appropriate people. Bill Scofield called at 14:28 and stated he was on his way to the location and also had a Vac Truck en route.</p> <p>Bill arrived on Location and stated that the Vac truck and a Backhoe were en route. Free standing fluid would be picked up today and they would start removing the contaminated soil. Fix the compromised berm. And tomorrow more work will continue.</p> <p>Alyssa Beard called and stated that she is going to fill out the spill report.</p> <p>A follow up site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petrie	05/05/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402390849	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142851
696301788	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142850