

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2020

Submitted Date:

05/06/2020

Document Number:

688307804

FIELD INSPECTION FORM

Loc ID 317166 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 94300
Name of Operator: WARD & SON* ALFRED
Address: P O BOX 737
City: OGALLALLA State: NE Zip: 69153

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Leonard, Mike		mike.leonard@state.co.us	COGCC FIU Acting Manager
Young, Rob		rob.young@state.co.us	COGCC EPS
Axelson, John		john.axelson@state.co.us	COGCC EPS Acting Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236964	WELL	PR	12/13/1979	OW	121-09464	WRIGHT 31-1	SI

General Comment:

Wildlife Mortality/Spill Inspection

At ~12:44 pm on 5/4/2020 inspector contacted COGCC EPS about dead ducks and birds observed in free oil on the Wright produced water pit.
At ~08:06 am on 5/5/2020 inspector contacted CPW officer for Washington County about the dead ducks and birds in the oil on the Wright pit and subsequently meet the officer at the pit. The CPW officer collected 7 of the ducks and birds as evidence. Two ducks and one other bird could not be retrieved because of the steep pit banks and were left there. The vac truck driver was on location and removing the free oil from the pit on the morning of 5/5/2020 when the inspector arrived. This removal of oil continued through the day. Most of the free oil was removed on 5/5/202 but the vac truck driver said that he would come back the morning of 5/6/2020 to verify that all the oil was removed. Approximately 100 bbls of oil was estimated to be removed from the surface of the pit.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil		>= 5 bbls	
Comment:	Approximately 100 bbls crude oil spilled into produced water pit. Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 906.b. Twenty-four hours for notification to COGCC and 72 hours to submit Initial Form 19 Report to COGCC. Notify landowner and Washington County LGD.		
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 906.b. Twenty-four hours to remove free fluids, 24 hours for notification and 72 hours for Initial Form 19 Report. 324A. POLLUTION a. The operator shall take precautions to prevent significant adverse environmental impacts to air, water, soil, or biological resources to the extent necessary to protect public health, safety and welfare, including the environment and wildlife resources, taking into consideration cost-effectiveness and technical feasibility to prevent the unauthorized discharge or disposal of oil, gas, E&P waste, chemical substances, trash, discarded equipment or other oil field waste.		Date: <u>05/05/2020</u>

In Containment: Yes

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	PIT		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	on treater		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:	bermed, shed, propane		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:	may be filled with oil, check prior to well startup				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:		may be filled with oil, check prior to well startup				
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 236964 Type: WELL API Number: 121-09464 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action:

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: Oil Accumulation: YES 2+ feet Freeboard: YES

Comment: See Spill section of inspection for removal of free fluids observed on pit. Stained soil ring remains inside pit walls that needs to be removed and properly disposed of (see attached photos). Pit berms are eroding into adjacent field and pasture (see attached photo).

Corrective Action: Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS. Maintain pit berms.

Date: 05/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402391685	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143614
688307806	Ward & Son*Alfred, Wright 31-1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143609