



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f(2).d.	Date:	09/08/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Equipment	#	Corrective Action	corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 251399 Type: WELL API Number: 123-19202 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

Facility ID: 292187 Type: WELL API Number: 123-26252 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

Facility ID: 293009 Type: WELL API Number: 123-26443 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      **Weather Conditions: sunny, dry ground                      On Monday, June 8, 2020 at approximately 11:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at SCHANK J 36-06, 35-21, 35-20 (PDC Energy), at location #: 336706 in WELD COUNTY Colorado.                      While there, I observed shut in wellheads.                      During this inspection the following possible compliance issues were observed:                      1. Stained soil at one wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes PER RULE 1002.F.(2).D. (Corrective Action Date: September 8, 2020) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	06/08/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402415820	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5168879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5168879</a>
679602831	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5168848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5168848</a>